E40100

Screw-in adapter for process sensors




Adapter SI0/M12x1/MS

Insertion depth

Accessories Items supplied

Remarks

Remarks Pack quantity [mm]



threaded connection M12 x 1

13.5; (measuring probe SID, SFD, TN)

sealings: 1, AFM

In applications >30 bar use a suitable high-pressure adapter.

1 pcs.