


E19907



Mounting clamp

Schelle mit Anschlag/M12/M18

Article no longer available - archive entry



Application

Design

with end stop

Mechanical data

Materials

PBT

Accessories

Accessories (supplied)

screws: 2 x M4 x 4

screws: 2 x 3 x 19, for M12 sensor

screws: 2 x 3 x 25, for M18 sensor

Remarks

Pack quantity

1 pcs.

Article no longer available - archive entry