ZC0019

Cleaning of pressure sensors intended for oxygen atmospheres (free from oil and grease)



Reinigung f. Sauerstoffeinsatz

No scale drawing available

Application		
Application		Cleaning of pressure sensors intended for oxygen atmospheres (free from oil and grease); up to a measurement range of max. 25 bar; для серій PG24, PK, PN2, PNU, PP, PT2, PT354, PT53, PT54, PT954, PTU4, PU54
Mechanical data		
Weight	[g]	2.87
Remarks		
Remarks		Cleaning can only be ordered together with a sensor.
		The corresponding sensor is delivered, specially marked and packed.