


Mounting set for photoelectric sensors

MOUNTING SET OH



Operating conditions

Ambient temperature	[°C]	-30...60
---------------------	------	----------

Mechanical data

Weight	[g]	10.1
--------	-----	------

Materials		ABS
-----------	--	-----

Remarks

Pack quantity		1 pcs.
---------------	--	--------