


# E40100



## Screw-in adapter for process sensors

Adapter SI0/M12x1/MS



### Application

|                       |                             |
|-----------------------|-----------------------------|
| Application           | for industrial applications |
| Media                 | liquids and gases           |
| Pressure rating [bar] | 30                          |

### Tests / approvals

|                              |   |
|------------------------------|---|
| Pressure Equipment Directive | A possible classification to PED depends on the application and has to be carried out by the user / operator. |
| Safety instructions          | The compatibility between medium and product material has to be checked in all applications.                  |

### Mechanical data

|                      |                                      |
|----------------------|--------------------------------------|
| Weight [g]           | 59.1                                 |
| Dimensions [mm]      | M18 x 1.5                            |
| Thread designation   | M18 x 1.5                            |
| Materials            | brass (2.0401)                       |
| Sensor connection    | M18 x 1,5 internal thread            |
| Process connection   | threaded connection M12 x 1          |
| Insertion depth [mm] | 13.5; (measuring probe SID, SFD, TN) |

### Аксессуары

|                |                  |
|----------------|------------------|
| Items supplied | sealings: 1, AFM |
|----------------|------------------|

### Remarks

|               |   |
|---------------|---|
| Remarks       | In applications >30 bar use a suitable high-pressure adapter. |
| Pack quantity | 1 pcs.  |